



## Specialty Products **FAQ**

Part number 87520

### Nissan Camber/Caster Kit

---

**Q1: What should I do if the cams seem too big for the frame brackets?**

**A1:** It seems that some trucks occasionally have the cam locators slightly closer together, which can cause the cams to seem like they don't fit. In these cases, SPC recommends lightly grinding down the normal 'bevel' around the edge of the cam until it is closer to a 'square' edge— this should reduce the diameter just enough for a better fit. Usually, only one or two cams (if any) might need this done.

