



Specialty Products **FAQ**

87550, 87555

xAxis® Joint Kits

Q1: Why are there only two bushings included in your kit when the lower control arm has 3 bushings?

A1: The two pivots we supply are direct replacements for the cross axis style joints used by the manufacturer in the lower control arm. The larger third bushing is a standard rubber design and does not wear nearly as much as the other two.

